

FLEET STATUS REPORT

7/28/2017

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
07/20/17	Fire	1800	Replace one tire off the vehicle.	0.50	\$152.13	D
			Preventive maintenance service. Check engine light - P0430 Bank 2 Catalyst Efficiency below limit. Troubleshoot, no PCM communication, found bad pin at			
07/20/17	Police	1813	OBDII connector.	2.50	\$37.71	D
07/20/17	Police	1812	Replace front pads and rotors.	1.50	\$189.80	D
07/20/17	Police	1807	Troubleshoot air conditioning problem.	1.00		D
			Mount and balance two new front tires. Preventive maintenance service.			
07/20/17	Police	1816	Pull rotors on all wheels. Road test. Clean-up tires and scrap.	3.50	\$529.98	J
07/20/17	DPW	320	Check out trash truck for use at water carnival. Air up all tires and check fluids.	3.50		J,P
			Check air bag light. Road call to Browns Mills Fire Company.			
			Start unit light went out and did not come back on. Scanned air bag computer for			
07/21/17	Fire	1891	codes, no codes found at present time.	2.00	\$0.00	DD,D
07/21/17	Police	1811	Install new air bag clock spring.	1.00	\$187.08	DD
			Flat tire at spillway, ran tire off bead.			
07/21/17	DPW	105	Called Tri-State for repair and jacked up tractor to get ready for Tri State	4.50	\$0.00	J,D,DD
			Move into shop and jacked up on blocks. Remove slack adjusters			
07/21/17	DPW	T-25	and all brake chambers. Replace grease fittings in S cam bushings.	3.50	\$0.00	J,D
07/21/17	Police	1804	Preventive maintenance service.	1.50	\$29.30	J
07/21/17	Water	72	Straighten right side rim to stop air leak.	2.00	\$0.00	J,D
07/21/17	Police	1802	Preventative maintenance service.	1.50	\$30.89	D
07/21/17	Police	1834	Repair interior light dimmer switch plug.	0.5	\$0.00	D
07/21/17	Police	18M3	Install and charge battery. Drain gas and get running. Check over unit.	1.5	\$0.00	D
07/24/17	DPW	25	Remove fuel feed line to pump and replace. Have one made.	1	\$0.00	J
07/24/17	Police	1813	Replace right rear tire, due to flat.	1	\$108.90	J
07/24/17	DPW	102	Remove and replace starter.	2	\$138.90	J,D
07/24/17	DPW	T-25	Install four new brake chambers, adjust brake and lube S cams. Air up all tires.	3.5	\$153.86	J,D
			Road call to Country Lakes Fire Dept. Check Water pump. Found front shaft			
07/24/17	Fire	1831	packing leaking. Contacted Blaze for quote and appointment.	2	\$0.00	DD
07/24/17	Police	18M3	Drain gas from carburetor and tank. Test battery - remove bad battery.	1	\$0.00	D
			install updraft oxygen sensors. Replace spark plugs and intake manifold gasket.			
07/24/17	Police	1811	Weld exhaust leak at muffler/tailpipe	3.5	\$308.69	D
07/24/17	DPW	Shop	Remove tags, check over scrap units in junk yard for sale.	0.5	\$0.00	D

**FLEET STATUS REPORT**

7/28/2017

<u>DATE</u>	<u>DEPT</u>	<u>VEHICLE</u>	<u>REPAIR</u>	<u>Hours</u>	<u>Parts Costs</u>	<u>MECH</u>
07/25/17	DPW	6900	Replaced damaged glad hand off truck. Hooked air lines from behind cab so they could move equipment.	1	\$0.00	J
07/25/17	DPW	Scrap	Stripped cars of radios and emergency lights and moved out into field for pick-up	6.5	\$0.00	J,D,DD
07/25/17	DPW	25	Hook up fuel lines and ran lines into five gallon bucket of fuel to bypass fuel tank, still no start.	1		J
07/25/17	Police	1813	Change motor mount. Replace starter	1.5	\$189.49	J
07/25/17	Rec	79	Drop off and pick up for lettering.	2	\$250.00	D,DD
07/25/17	DPW	107	Tilt cab, drain hydraulics. Remove and replace two leaking hydraulic suction screens and o-rings.	2.5	\$10.28	D
07/25/17	Police	1805	Check engine light on. P0300 misfire detected, P0306 cylinder 6 misfire detected.	0.5	\$0.00	D
07/26/17	Water	Shop	Unload chlorine into storage shed. Load empty containers on pallet.	1	\$0.00	J,D
07/26/17	Police	18M2	Put fresh fuel in tank. Replace battery and rear strobe light bulb. Test drive.	1	\$0.00	D
07/26/17	DPW	109	Replace fuel shut off solenoid. Jump start unit.	0.5	\$156.25	D
07/26/17	DPW	107	Replace leaking o-rings at hydraulic tank suction screens. Refill with hydraulic oil that was saved. Repair cab door latch. Remove rear belly pans and power wash around repair area.	4	\$15.10	D
07/26/17	DPW	T-16	Flip six teeth. Service are filters	2.5	\$69.12	J,D
07/26/17	DPW	T-32	Lower pintle hook. Repair crushed service and emergency air lines	0.5	\$0.00	J
07/26/17	DPW	25	Found wire pulled out of ECM plug. Road test. Clean up.	3.5	\$0.00	J,D
07/26/17	DPW	100	Reattach fuel lines to tank.			
			Fit new bearing to cutter shaft and install.	1	\$213.18	J
			Total Hours Worked	74.00		
			Time Off (e.g., sick, vacation, etc...)	40.00		
			Misc. Time (e.g., Class, CDL Drug Test, etc...)			
			<b>TOTAL HOURS</b>	<b>114.00</b>		
			<b>TOTAL PARTS COST</b>		<b>\$2,770.66</b>	