

FLEET STATUS REPORT

10/17/2016

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
10/06/16	Water	69	Replace four way flasher delay, install two self tappers in sill plate.	0.50	\$16.14	J
10/06/16	PW	23	Jump start and put away.	0.50	\$0.00	J
10/06/16	PW	105	Install pre mounted front tires.	1.00	\$0.00	J
10/06/16	PW	Shop	Dump trash, clean shop.	1.00	\$0.00	D
10/06/16	Police	1809	Replace spark plugs, heater hoses, scan and clear codes, test drive.	4.00	\$174.40	D
10/06/16	PW	36	Replace master cylinder, R.F. brake line, one freeze plug on block,	3.50	\$48.90	J,D
10/06/16	PW	5	PM, remove seat for repair.	1.50	\$35.02	J
10/06/16	Police	1813	Take to Tri-State tire for tire sensor check.	1	\$0.00	D,DD
10/06/16	PW	503	Pick up battery, install battery.	0.5	\$145.99	D
10/07/16	PW	4	Mount and balance 4 tires.(New at tire mounting).repair exhaust leak.	4	\$502.52	D
10/07/16	PW	7	PM service, wash truck.	2.5	\$22.21	D,J
10/07/16	PW	9	Check for leaks on rear axle.	0.5	\$0.00	D
10/07/16	PW	21	Clean up fuel tank to be installed and truck frame.	6	\$0.00	J
10/11/16	PW	101	Replace L.R. tail light bulb.	0.5	\$1.99	DD
10/11/16	PW	206	Pick up and install unit I.D. stickers	0.5	\$4.14	DD
10/11/16	PW	9	Check rear for noise, Noise is in the tires.	0.5	\$0.00	DD
	PW		1. To Al's interiors, pick up seat for #5. 2. To Clydesdale, pick up oxygen and acetylene. 3. To Hainesport Truck, have hydraulic hose made for Case #35.	2	\$0.00	
10/11/16		Shop				DD
10/11/16	PW	Shop	Unload lumber delivery.	0.5	\$0.00	J
10/11/16	PW	21	Install fuel tank, adapt lines for new routing.	4.5	\$22.46	J
10/11/16	PW	5	Replace rotted out dipstick tube.	1.5	\$12.82	J
10/11/16	PW	7	Remove welding tanks to be filled. Reinstall.	0.5	\$0.00	D
10/11/16	PW	35	Replace leaking hydraulic cooler hose.	2	\$265.92	D
10/11/16	PW	23	Charge batteries,	0.5	\$0.00	D
10/11/16	PW	107	Road Call: Hydraulic leak had to bring back to shop due to size of job.	1	\$0.00	D,DD
10/11/16	PW	1813	Pick up from Tri-State after tire sensor repair.	1	\$149.95	D,DD
10/11/16	Police	1801	Check sulfur smell, replace battery.	0.5	\$125.13	D
10/11/16	PW	220	Charge batteries, get unit running.	0.5	\$0.00	D
10/12/16	PW	35	Reinstall rebuilt parking brake caliper and adjust.	2	\$0.00	D
10/12/16	PW	107	Replace angle cylinder hydraulic hoses.	2.5	\$0.00	D
10/12/16	PW	Shop	Replace engine oil drum in shop.	0.5	\$0.00	D
10/12/16	Code	50	PM service, check and plug R.F. tire.	1.5	\$18.58	D
10/12/16	PW	23	Hook up 2way radio power to ignition side of switch.	0.5	\$0.00	J
10/12/16	PW	13	Jump start.	0.5	\$0.00	J
10/12/16	PW	10plow	Drill holes in replaced frame for rubber edge.	1	\$0.00	J

FLEET STATUS REPORT

10/17/2016

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
10/12/16	Fire	1804	Check brakes and remove rears for replacement.	1	\$0.00	J
10/12/16	PW	5	Install drivers seat, pull wheels check brakes, test drive.	1.5	\$0.00	J
10/12/16	PW	21	Finish installing fuel tank, test drive.	1.5	\$0.00	J
10/12/16	PW	19	Remove transfer case driveshaft.	1	\$0.00	J
10/12/16	PW	24	Replace L.R. tail light bulb.	0.25	\$1.99	DD
10/12/16	PW	Shop	1. To Hainesport Truck, have hydraulic hoses made for Case Loader. 2. Pick up parts at Parts Connection for shop and stock.	2	\$0.00	DD

