

Fleet Status Report

3/3/2016

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
02/25/16	PW	101	Remove and replace roof strobe light, remove and repalce all wiring, remove and replace switch. (For strobe light)	3.00	\$95.28	C
02/25/16	PW	15	PM service, remove and repair thrid brake light, remove and replace r/front marker light, re-set oil life to 100%.	3.00	\$54.41	C
02/25/16	PW	20	Disassemble rear brake backing plates, clean backing plates. Install new parts on rear backing plates.(Brake shoes, springs, wheel cylinders). Remove and install new front shocks and hardware. Clean and repack front wheel bearings. Install front rotors. Install new front brake calipers and rubber lines.	9.50	\$368.94	J,D
02/25/16	PW	112	PM service, reset oil life to 100%	2.00	\$38.89	D
02/25/16	PW	15	Road call to BMIA Building soft tire. Air up and get back to shop.	1.00	\$0.00	C,J
02/25/16	PW	Shop	Load Truck #24 with cold patch.	0.50	\$0.00	D
2/25/2016	PW	15	Plug tire. Not plugable tire to be replaced.	0.50	\$1.78	D
02/26/16	PW	20	Fabricate rear brake lines, bend , cut, reflare as needed to fit.	2.00	\$4.39	D
02/26/16	PW	15	Remove and replace L/rear tire. Mount and balance new and re-install.	1.00	\$119.97	D
02/26/16	PW	Shop	Check vehicles in fleet for current registrations, inspections, and insurance cards	2.00	\$0.00	A
02/26/16	Insp.	41	PM service. Remove 3rd brke light for repairs. Not repairable (sealed LEDS) light needs to be repalces. Parts ordered.	2.50	\$29.69	A
02/26/16	PW	20	PM service. Remove and repair oil filler tube, Re-install.	2.50	\$23.19	J
02/26/16	Water	61	Remove and replace fuel filter, replace fuel filter clips.	1.00	\$19.02	C
02/26/16	Police	1813	Remove and replace engine cooling fan, module, thermostat, and o ring. Add antifreeze as needed. Run vehicle and check for leaks. Put back in service.	2.50	\$408.33	C
02/26/16	PW	101	Check vehicle for braking problem. Camplaint of rear brake problem. Put vehicle on lift, pull all wheels inspect brakes. No problem found. Put wheels back on and test drive vehicle. Vehicle pulls to right when brakes applied. Front brake parts ordered.	2.00	\$0.00	C
02/26/16	PW	20	Install master cylinder, flush complete brake line system. Start installation of brake and suspension components.	4.00	\$0.00	J
02/26/16	PW	Shop	Put insurance cards in Police motorcycles.	1.00	\$0.00	D
02/26/16	PW	31	Jump start.	0.50	\$0.00	J
02/26/16	PW	Shop	Remove old hydraulic hose reel. In stall new reel. Clean wall from old fluids, oil grease, etc. Clean all air hose reels and hoses, inspect hoses. Fabricate holder and mount for oil wrenches. Remove trash and clean shop.	5.00	\$429.00	D,A,C

Fleet Status Report

3/3/2016

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
02/29/16	PW	Shop	Drain water out of shop air compressor, check oil level in compressor, clean and service in line air dryer and oiler.	1.00	\$7.20	D,A
02/29/16	PW	15	Remove and replace 3rd brake light assemble. Remove, replace Right rear tire Mount and balance and re-install on vehicle.	1.00	\$184.93	A
02/29/16	Police	1805	PM Service.	2.00	\$32.32	A
02/29/16	Police	1803	PM Service. Hook up to scanner for check engine light. Small evap leak. Re-set light run vehicle no light. Will monitore. Remove and replace headlight socket and wiring harness for Right headlight.	3.00	\$47.05	A
02/29/16	PW	12	Trouble shoot power steering problem. Need high pressure line. Parts ordered.	1.00	\$2.22	D
02/29/16	PW	16	Repair left rear turnsignal	0.50	\$0.00	D
02/29/16	PW	3	Jump start.	0.50	\$0.00	D
02/29/16	PW	24	Check front and rear leaf springs.	0.50	\$0.00	D
02/29/16	PW	4	Trouble shoot power steering problem. Need high pressure line. Parts ordered.	1.00	\$2.22	D
02/29/16	PW	20	Install rear leaf springs attach rear brakes backing plates and brakes.	4.50	\$825.64	J
02/29/16	PW	T-3	Repair and weld clean out door on bottom of chipper. Install new hinges.	2.00	\$16.09	J
02/29/16	PW	4	Remove and replace power steering high pressure hose, add power steering fluid as needed. Clean throttle body plate, remove and replace air filter.	1.5	\$43.08	D
02/29/16	Police	1813	Remove and repalce blower motor and blower motor resistor	1.5	\$81.42	D
03/01/16	PW	204	Install new rubber plow blade and all hardware.	1.5	\$256.40	C
03/01/16	PW	13	Lock out tag out, brake problem.	0.5	\$0.00	D
03/01/16	Insp.	41	Remove and replace Third Brake light assembly.	1	\$107.50	A
03/01/16	PW	36	PM Service.	2	\$26.65	A
03/01/16	PW	13	Trouble shoot brake problem. Remove and repair rear brake line. Bleed brakes, add fluiud as needed.	4	\$11.74	A,C
03/01/16	PW	23	Charge batteries and get running. Radio needs to be wired to ignition. To be scheduled.	0.5	\$0.00	D
31/16	PW	20	Install cleaned and packed wheel bearings, new grease seals. Install rear drums, set bearing adjustment. Bleed complete brake system, adding fluid as needed.Remove and replace crank case breather air filter and hose. Test Drive Vehicle has no body running lights, to be repaired.	11.5	\$14.50	J,D
03/01/16	PW	12	Remove and replace pressure side power steering hose from power steering pump to brake booster.	2	\$55.35	C
03/01/16	PW	101	Remove and replace front brake pads, calipers and hoses. Bleed brake system, add brake fluid as needed.	3	\$222.90	C,A

Fleet Status Report

3/3/2016

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
03/02/16	PW	11	Test drive throttle response problem. Couldn't duplicate. To be put on scanner.	1	\$0.00	D
03/02/16	PW	20	Repair running lights. Remove and replace Powere steering belt, add Lucas power steering treatment.	4.5	\$21.81	J,D
3/2/16	PW	Shop	Trouble shoot troller motor not operating. Disassemble control handle, switch are burnt up. Disassemble motor bottom end, brushes are severly worn, signs of heat and distortion on armature and stator. Needs to be replaced not worth repairing.	2	\$0.00	D
03/02/16	PW	17	Take to Creekside Glass for windshield replacement. Pick up when completed.	2	\$335.00	A,D
03/02/16	PW	11	Bring vehicle to shop and put on scanner retrieve Codes for no gas pedal response. Codes for gas pedal present. Parts ordered.	1	\$0.00	C
03/02/16	PW	32	Remove and repalce front brake pads and rotors.	1.5	\$88.29	C
03/02/16	PW	26	Remove and replace upper tarp swing arm.	1	\$130.00	C
03/02/16	PW	13	Fabricate mounting Plate and re-install tag that was off.	1	\$0.00	C,D
03/02/16	PW	36	Troubleshoot no hazard lights. Remove and replace flasher.	2	\$15.15	C,D
03/02/16	Fire	1601	Pick up from Craigs after air bag repair.	1	\$201.76	D,A
03/02/16	PW	19	Repair leaking water pipe high pressure.	2	\$0.00	J
03/02/16	PW	23	Road call. Vehicle will not start, Get vehicle running and get back to shop.	3	\$0.00	J,C,A,D
03/02/16	PW	Shop	Office Time.	4	\$0.00	A
03/02/16	PW	Shop	To Advance Auto Parts for Parts.	0.5	\$0.00	J

Projected work;
 Services;1610, 1618, 16, 14, 6, 63, 10.
 Repairs; 28, 22, 21, 33, 24, T-9, 1810, 1804.

PM - Preventive Maintenance
 LED - Light Emiting Diode

Total Hours Worked	118.00
Time Off (e.g., sick, vacation, etc...)	16
Misc. Time (e.g., Class, CDL Drug Test, etc...)	

<u>DATE</u>	<u>DEPT</u>	<u>VEHICLE</u>	<u>REPAIR</u>	<u>Hours</u>	<u>Parts Costs</u>	<u>MECH</u>
-------------	-------------	----------------	---------------	--------------	--------------------	-------------

TOTAL HOURS 134.00

TOTAL PARTS COSTS \$4,322.11