

Fleet Status Report

3/10/2016

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
03/03/16	PW	12	Remove right front tire, put in water tub to find leak, plug tire. Repair plow lights. Broken wire.	1.50	\$0.89	D
03/03/16	PW	18	Remove right front tire, put in water tub to find leak, plug tire. Remove and Replace plow rubber blade. Remove and repalce front plow lights, check lighting system.	3.00	\$253.66	C,D
03/03/16	Police		Go to impound yard and jump start a vehicle for Police.	0.50	\$0.00	D
03/03/16	PW	204	Position plow slides to proper adjustment.	0.50	\$0.00	D
03/03/16	PW	20	Troubleshoot horn, not working. Remove steering wheel to acess horn mechanism. Mechanism needs to be repalced. Parts ordered.	3.00	\$0.00	J,D
03/03/16	PW	23	Remove starter, reclock starter nose for correct fit, Install starter.	4.00	\$325.00	J
3/3/2016	PW	11	Remove and replace gas pedal. Road test. Good put back in service.	1.00	\$164.83	C
03/03/16	Police	1839	Test drive , compalint of transmission noise and performance problem. Could not duplicate at this time.	1.00	\$0.00	C
03/03/16	Fire	1602	Put vehicle on lift and check for complaint of brake noise. Vehicle has inner brake pad ware on Left front wheel. Troubleshoot inoperative heating blower motor. Parts ordered.	1.00	\$0.00	C
03/03/16	PW	32	Fuel vehicle.	0.50	\$0.00	C
03/03/16	PW	31	Jump start and get running. Check charging system. Good.	1.00	\$0.00	C
03/04/16	Fire	1602	Remove and repalce, front rotors and brake pads. Troubleshoot heater blower motor system. Remove and replace heater blower motor and resistor.	6.50	\$251.19	C,D
03/04/16	Police	1809	Troubleshoot overheating problem, and no heat. Pressurize system and look for leaks. Found tees for dual heating system at heater core leaking. Start disassembling to gain access to tee fittings.	3.00	\$41.79	A,D
03/04/16	PW	Shop	To Lucas Chevy to pick up parts.	1.00	\$0.00	A,D
03/04/16	PW	34	Jump start	0.50	\$0.00	A
03/04/16	Police	1808	Remove and replace headlight.	0.50	\$29.89	D
03/04/16	PW	13	Pick up from Tri-State Tire after new tires installed.	2.00	\$877.60	A,D
03/04/16	Police	1830	Troubleshoot non working siren. Trace power wire from console to power supply. Clean and service fuse holder, replace fuse. Works	1.00	\$0.00	D
03/04/16	Cert	200	Get running and move down back to yard.	2.00	\$0.00	A,D
03/04/16	PW	37	Tighten throttle linkage inside cab.	0.50	\$0.00	D
03/04/16	PW	Shop	Hand in CDL Physical Paper work to front office.	0.50	\$0.00	D

Fleet Status Report

3/10/2016

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
03/04/16	PW	24	Start troubleshooting for strobe light problem and non working back up alarm. Not completed.	1.00	\$0.00	J
03/04/16	PW	20	Remove and replace turnsignal switch in steering colum to repair horn. Grease steering shaft. Take to State Inspection Pass.	2.50	\$82.42	J
03/04/16	PW	16	PM service, repair rear tail light wiring, remove and replace marker light.	4.00	\$136.62	J
03/04/16	PW	Shop	Pick up used tires, put in tire trailer. Pick up all scrap metal and but in metal recycle box. Clean up around shop.	1.00	\$0.00	C
03/07/16	Fire	1602	Do inspection of front end. Vehicle needs lower ball joints on left and right. Parts ordered. Adjust air pressure all tires.	1.00	\$0.00	C
03/07/16	Police	1809	Remove and replace tee fittings at heater core for dual heating system. Top off antifreeze as needed.	2.50	\$7.28	D
03/07/16	Water	71	Pull vehicle in to shop and put on lift. Check for exhaust noise, (rattle). Noise is coming from catalytic convertors. To be repair under emmissions warrenty at Dealer. Remove all tires and inspect brakes. Rear brakes need repair. Disassemble rear brakes. Parts ordered.	2.00	\$0.00	C
03/07/16	Fire	1602	Put vehicle on lift and disassemble front end to install lower ball joint. Remove and install new lower ball joints left and right. Reassemble front end.	5.00	\$84.64	C,D
03/07/16	Police	1830	Test drive for transmission problem. Can not duplicate problem.	0.50	\$0.00	C
03/07/16	Fire	16	Take to Tri-State for front end alignment after repairs.	1	\$0.00	C,D
03/07/16	PW	24	Troubleshoot strobe lights not working, back up alarm and marker lights. Disassemble wiring harness as needed to troubleshoot.	7.5	\$47.13	J,D
03/08/16	PW	28	Troubleshoot snow valve in air cleaner. Has a bad gear box to be repaired under warrenty.	1	\$0.00	D
03/08/16	PW	22	Adjust front and rear brakes. Install clamp on exhaust hanger.	1.5	\$8.69	D
03/08/16	PW	2	Jump staer and bring down to shop. Charge battery. Troubleshoot shutting off proplem. Not complete.	1	\$0.00	D,C
03/08/16	PW	Shop	Dealer training on new skid steer.	1.5	\$0.00	D,J,C
03/08/16	PW	32	Remove and replace right front door handle.	2.5	\$28.79	C,D
03/08/16	Fire	1602	Pick up from Tri-Statr Tire after front end alignment. Return to Fire House.	1	\$89.95	C,D
03/08/16	Water	71	Remove and replace rear brake pads and rotors.	1.5	\$94.09	C
03/08/16	Water	71	Take to Medford Ford for repairs under warrenty.	3	\$0.00	D,C
03/08/16	PW	24	Re-assemble wiring harness and tie up. Repaired marker light, repaired bad grounds that were found. Remove and replace 7 pole trialer light plug with boot.	5	\$14.37	J
03/08/16	PW	37	Road call for engine noise. Possible fuel problem. Grt back to shop. Not completed.	0.5	\$0.00	J

Fleet Status Report

3/10/2016

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
03/08/16	Police	1809	Test drive after repairs. Put back in service.	0.5	\$0.00	D
3/8/16	PW	32	Adjust all tire air pressures.	0.5	\$0.00	C
03/09/16	PW	37	Troubleshoot engine making noise. Loosen injector lines and found number 4 cylinder making noise. Pulled injector and found tip missing. Parts ordered for repairs.	5	\$0.00	J
03/09/16	Admin	2	Check for vehicle shutting off problem. Vehicle runs fine. Can not duplcte problem. Go to Mt Holly Kawaski-Suzuki. Pick up plow parts for Polaris Quad.Put parts in Quad shed when brought back.	0.5	\$0.00	A
03/09/16	PW	Shop	Quad shed when brought back.	1.5	\$0.00	A
03/09/16	PW	31	Road call to BMIA Building to air up tire.	1	\$0.00	A
03/09/16	PW	35	Jump start get running, check charging system, Ok Air up tires.	1.5	\$0.00	A
03/09/16	PW	204	Put vehicle on scanner. Code for fuel tank unable to build up vaccum. To dealer for repairs under warrenty.	0.5	\$0.00	C
	Police		Put on scanner and check for Codes. Codes present for misfire and Mass air flow sensor.Removed and Replaced all coil packs with known good used ones. Removed and replaced Mass air flow sensor , removed and replaced crank shaft sensor. removed a valve cover to inspect valves on driver side. No problem found.	7	\$25.49	
03/09/16		1806	Not complete.			C,A
03/09/16	PW	31	Road call to BMIA Building take hydraulic fluid for Loader.Check for leaks and top off as needed.	2	\$37.60	A,J

Projected work;  
 Services;1610, 1618, 14, 6, 22, 63.  
 Repairs; 28, 22, 33, T-9, 1810, 1804, 67.

Total Hours Worked

101.00

Fleet Status Report

3/10/2016

<u>DATE</u>	<u>DEPT</u>	<u>VEHICLE</u>	<u>REPAIR</u>	<u>Hours</u>	<u>Parts Costs</u>	<u>MECH</u>
			Time Off (e.g., sick, vacation, etc...)	24		
			Misc. Time (e.g., Class, CDL Drug Test, etc...)	1.5		
				<b>TOTAL HOURS</b>	126.50	
				<b>TOTAL PARTS COSTS</b>	\$2,601.92	