

Fleet Status Report

4/28/2016

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
04/14/16	Police	509	Brakes-Pulley, Master Cylinder Clutch, Shoes, Shoe hardware kit	6.50	\$121.85	C
04/14/16	PW	22	Repairs - battery cables and P/S lines	6.50	\$71.79	J
04/14/16	Water	61	Remove power steering rack and pump	5.00		D
04/14/16	PW	Shop	Pick up tires from Tri-State	0.50		D
04/14/16	PW	26	Checked out antifreeze leak - Needs radiator	1.00		C/D
04/14/16	PW	23	Charged batteries, get running	0.50		D
04/14/16	PW	Shop	To Advanced Auto for parts	0.50		A
04/14/16	PW	Shop	Office time	5.50		A
04/15/16	PW	102	Test drive. Noticed vibration at 45 mph. Recommend u-joints.	0.50		C
04/15/16	PW	Shop	Put tires in trailer	1.00		C/D
04/15/16	PW	22	Repaired another broken wire for starter relay	3.50		D/J
04/15/16	PW	26	Removed radiator	5.00		D/J
04/15/16	Water	69	Replaced oxygen sensors. Vendor sent wrong downstream sensor. Re-ordered parts.	3.50	\$91.26	C
04/15/16	PW	T-1	No start problem. Replaced battery, check starting and charging system.	1.50	\$97.62	D
04/15/16	Water	61	Continued repairing steering rack and pump	2.00		D
04/15/16	Police	509	Bled clutch master cylinder and slave cylinder. Test drive.	2.50		C/D
04/18/16	Water	61	Clean, inspect, repair and start re-installing power steering rack and pump	6.50		D
04/18/16	PW	31	Went to Giles and Ransom to look at loader boom	3.50		J
04/18/16	PW	22	Continued repairing wiring and sight glass on hyd. Tank	3.00		J
04/18/16	PW	Shop	Cut and weld on sifter	2.00		A
04/18/16	Police	1802	Lock out/tag out	0.50		A
04/18/16	Water	64	Lock out/tag out	0.50		A
04/18/16	Police	1802	R&R left, rear tire. Mount and balance. New valve stem.	0.50	\$108.77	A
04/18/16	PW	Shop	Repair tire spaces for tire machine	1.00		A
04/18/16	Police	1802	Check engine light. Various random codes from scanner. Test drive-trans slipping. Checked fluid-brown and burnt odor.	1.00		A
04/18/16	Water	69	Installed oxygen sensor	1.00	\$74.04	C
04/18/16	Police	1803	Check engine light. Two overheating codes. Pressure tested coolant system. Recommend coolant fans and module be replaced.	2.00		C
04/19/16	PW	37	Prepare for engine removal. Re-assemble head and valve cover.	5.50		J
04/19/16	PW	22	Install new circuit breaker.	1.00	\$54.44	J
04/19/16	PW	Shop	Weld sifter	5.00		A
04/19/16	Fire	1632	Checked over for repairs and brought back to shop	1.00		D/C
04/19/16	Fire	1693	Install hand held radio charger	2.00	\$0.65	D/C

Fleet Status Report

4/28/2016

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
04/19/16	Fire	1636	Checked over for repairs	1.00		D/C
04/19/16	PW	38	Checked hydraulic leak	2.00		A/D
04/19/16	Water	61	Finished putting front end back together. Filled power steering fluid and cooling	3.5	\$7.80	D
04/19/16	PW	102	Removed drive shaft. Attempted to remove u-joint.	1		D/C
04/19/16	Police	1803	light. Test drive.	3	\$388.11	C
04/20/16	PW	Shop	Weld sifter	4		A
04/20/16	PW	26	Installed new radiator. Ordered new brake light switch. Cleaned up.	6.5	\$1,314.67	J
04/20/16	Fire		Travel to BMFH, Blaze for charger for 1636 and Advanced Auto for u-joint for 102	1		D
04/20/16	Fire	1601	Took to Lucas Dodge for air bag light	2		A/D
04/20/16	Fire	1632	Picked up from BMFC, replaced center spindle hub cap, filled with gear oil, checked for leaks, cleaned tire and rim. Returned to BMFC.	3.5	\$29.18	D/A/C
04/20/16	Fire	1636	Travel to CLFH, checked autocharge system. Not working; will not charge battery.	3		D/A/C
04/20/16	Water	64	R&R front brakes, rotors, hoses and calipers. PM service. R&R wiper blades.	4.5	\$354.50	C
04/20/16	PW	32	Fueled up	1		D/C

Total Hours Worked	117.50
Time Off (e.g., sick, vacation, etc....)	13
Misc. Time (e.g., Class, CDL Drug Test, etc....)	0

TOTAL HOURS 130.50

TOTAL PARTS COSTS \$2,714.68