

Fleet Status Report

3/23/2016

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
03/10/16	Police	1806	Install valve cover and coil packs. Trouble shoot engine problem.	6.00	\$342.36	A, D, C
03/10/16	PW	14	Preventive maintenance service. Remove and replace fuel filter.	3.00	\$49.59	D, C
03/10/16	PW	7	Fuel up	0.50		C
03/10/16	PW	T-32	Clock right rear tire so valve stem lines up with hole.	1.00		C, J
03/10/16	Water	67	Find 4 good rims. Take to Tri-State to switch to good rims.	0.50		J
03/10/16	Police	1801	Replace front bottom spoiler and secure.	0.50	\$0.40	D
03/10/16	Fire	1618	Preventive maintenance service.	2.00	\$32.90	D
03/10/16	PW	T-9	See work request. Check belts.	1.00		J
03/10/16	PW	Shop	Load tires and rims for 67 and take to Tri-State.	2.00		C, D
03/10/16	PW	205	Weld hook in bucket.	3.50	\$15.00	J
03/10/16	PW	31	Road call - oil and hydraulic leak.	1.00		J
03/10/16	PW	22	Check shield for exhaust stack.	0.50		A
03/10/16	PW	Shop	Go to Hainesport truck for hydraulic hose.	1.50		A
03/10/16	PW	Shop	Training on the Falcon.	1.00		A, D
03/11/16	PW	37	Prep engine for repair.	2.00		J
03/11/16	PW	Shop	Assist with welding bottoms for fence poles.	1.00		D
03/11/16	PW	T-9	Make parts list.	1.00		J
03/11/16	PW	31	O-rings on front bucket hydraulic lines.	1.00		A, D
03/11/16	PW	Shop	To Browns Mills Fire Company and Country Lakes Fire for 1610.	1.00		D, C
03/11/16	PW	31	Replace couplers on hydraulic lines for front bucket.	4.00	\$157.37	A, D
03/11/16	PW	T-4	Air up trailer tires.	0.50		D
03/11/16	PW	Shop	Unload tires and rims back into tire trailer.	1.00		D, J
03/11/16	PW	16	Repair left rear turn signal.	0.50	\$1.83	D
03/11/16	Water	old 63	Preventive maintenance service.	3.50	\$98.24	C
03/11/16	PW	10	Preventive maintenance service.	2.50	\$181.34	D
03/11/16	PW	Shop	Advance Auto to pick up parts.	0.50		C
03/11/16	PW	Shop	Assemble and install new pump for antifreeze barrel.	0.50	\$45.99	J
03/11/16	PW	Shop	Repair hose reel to air compressor.	1.5		A
03/11/16	PW	Shop	Office Time	2		A
03/11/16	Water	67	Pick up from Tri-State for further repairs.	1		A, D
03/14/16	Fire	1610	Preventive maintenance service. Replaced brake line. Bled ABS pump with scan tool.	5.5	\$56.99	A, C
03/14/16	PW	Shop	Advance Auto to pick up parts.	0.5		C
03/14/16	Police	1839	Driver side door key lock cylinder not working. Removed, replaced and put back together with rivet gun.	5.5		A
03/14/16	PW	37	Install 6 new injectors, adjust valves, reassemble.	6.5	\$521.94	J

Fleet Status Report

3/23/2016

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
03/14/16	PW	Shop	Locate wires on 19 controller.	1		D
03/14/16	PW	19	Install rewired pendant. Tear down old controller. Make a wiring diagram. Clean components. Reassemble components in new pendant. Test for proper operation.	4.5	\$147.78	D
03/14/16	PW	3026	Jump start and relocate beast.	1		D
03/14/16	PW	Shop	To Advance Auto to pick up parts.	0.5		C
03/15/16	Water	67	Disassemble and remove hub assembly. Clean and inspect hub spindle, brakes and drum. Clean and polish oil seal, sealing area.	2	\$173.37	D
03/15/16	Police	1830	Check siren and emergency light circuit. Change out circuit breaker.	1.5	\$2.34	D
03/15/16	Police	1839	Air conditioning high side running over 500 PSI. Has blockage on high side.	1		D
03/15/16	Water	71	Pick up from Medford Ford. Tire pressure light on. Vehicle inspection.	4		A, D
03/15/16	Fire	1603	Jump start. Hook up scanner for check engine light. Drive to get radiators monitors up. Take to state inspections-pass.	2.5		A
03/15/16	Police	1816	Hook up scanner for check engine light. Take to state inspection-pass.	2.5		A
3/15/2016	Police	1805	Remove and replace left front headlight bulb. Remove and replace front brake pads. Remove and replace front hub bearings. Tightened up bolt for computer bracket. Test drive.	5.5	\$12.58	C
3/15/2016	Fire	1610	Test drive.	0.5		C
3/15/2016	Police	1801	Mount tire.	0.5		C
3/15/2016	PW	37	Complete assembly of motor. Repair steps. Clean up. Test drive.	3		J
3/15/2016	PW	Shop	Empty trash. Change oil drum.	1		J, C
3/15/2016	PW	37	Preventive maintenance service.	3	170.83	J
3/16/2016	PW	Shop	Locate and load metal for 106 bucket job; bring around to work site with forklift.	0.5		D
3/16/2016	PW	12	Inflate tire and bring into garage.	0.5		D
3/16/2016	PW	t-2	Wire trailer side light harness.	1	5.95	D
3/16/2016	Water	67	Install new hub, pack bearings, install oil seal, adjust bearings, adjust brakes, install axle, wheels and fill rear with gear oil.	4.5	60.43	D
3/16/2016	PW	Shop	Office time.	5		A
3/16/2016	PW	Shop	Repair welding shield.	0.5		A
3/16/2016	PW	37	Finish installing sheet metal.	1		J
3/16/2016	PW	106	Go to BMIA Building to measure bucket. Cut bottom out of bucket. Grind welds.	5.5		J

Total Hours Worked	118.00
Time Off (e.g., sick, vacation, etc....)	10.5
Misc. Time (e.g., Class, CDL Drug Test, etc....)	

