

Fleet Status Report

10/15/2015

| DATE | DEPT | VEHICLE | REPAIR | Hours | Parts Costs | MECH |
|----------|--------|---------|--|-------|-------------|------|
| 10/08/15 | PW | 26 | Remove tarp and replace tarp and passenger side arm. | 2.00 | \$257.75 | R |
| 10/08/15 | PW | 10 | Seal oil pan. | 1.00 | \$7.49 | R |
| 10/08/15 | PW | Shop | Remove 2 truck beds from trailer. | 1.00 | \$0.00 | R |
| 10/08/15 | PW | 29 | Check all fluids add as needed. Road test. | 1.00 | \$32.78 | J |
| 10/08/15 | PW | T-2 | Repair trailer plug. | 0.50 | \$0.00 | J |
| 10/08/15 | PW | T-31 | Weld on 21 new bit holders. | 4.00 | \$273.63 | J |
| 10/08/15 | PW | 16 | Remove fuel tank and sender. Tank full of rust and tank coating, sender missing parts. | 1.00 | \$0.00 | J |
| 10/08/15 | PW | T-102 | Repair wiring on trailer. | 0.50 | \$0.00 | D |
| 10/08/15 | Police | 1833 | Set monitors. State inspection. | 1.50 | \$0.00 | D |
| 10/08/15 | PW | 101 | Take to Tri-State have TPMS Re-Set. Pick up when done. | 2.00 | \$44.50 | D,R |
| 10/08/15 | Fire | 1615 | To BMFH check generator. Been repaired by Blaze on numerous occasions. | 2.00 | \$0.00 | D,R |
| 10/08/15 | PW | 7 | Fuel up truck, generator/welder, air compressor and spare tank. | 0.50 | \$0.00 | D |
| 10/08/15 | PW | Shop | Go to O'Briens and pick up supplies to do frame on Trk #23. | 0.50 | \$12.93 | D |
| 10/08/15 | Police | 1800 | Wipers will not turn off. (need) pulled fuse. Parts ordered. | 0.50 | \$0.00 | D |
| 10/08/15 | Police | 1813 | Continue front end rebuild. | 1.00 | \$0.00 | D |
| 10/09/15 | PW | 23 | Continue install of new bed. | 10.50 | | C,J |
| 10/09/15 | PW | 22 | Tighten clamps on PTO suction hose at PTO, possible pump leak will monitor. | 0.50 | \$0.00 | J |
| 10/09/15 | PW | 16 | Install new fuel tank and sender. | 2.00 | \$1,256.74 | J |
| 10/09/15 | Police | UC | Air up tires and put back in yard. | 0.50 | \$0.00 | D |
| 10/09/15 | PW | Shop | Place oil drums in storage trailer, do trash run, remove scrap metal and tires, clean up shop. | 2.00 | \$0.00 | D,R |
| 10/09/15 | Police | 1816 | Remove spare, mount tire on new rim w/TPM balance install back in vehicle. | 1.00 | \$223.21 | D |
| 10/9/015 | Police | 1803 | Pick up from Craigs, Program PCM | 1.00 | \$130.00 | D,R |
| 10/09/15 | Police | 1802 | To state inspection. Pass | 1.00 | \$0.00 | D |
| 10/09/15 | Fire | 1692 | Check and clean throttle plate, replace air filter. | 1.50 | \$32.13 | D |
| 10/09/15 | Fire | 1615 | Meet with Blaze Tech at BMFC go over generator problem. | 3.00 | \$0.00 | D,R |
| 10/09/15 | Police | 1813 | Assemble and install 2 ner front struts. | 2.00 | \$211.96 | R |
| 10/09/15 | Police | 1804 | Install provided Police radio antenna. | 0.50 | \$0.00 | R |
| 10/09/15 | Police | 1818 | R&R heater hoses and T,s top off fluids. | 2.00 | \$145.13 | R |
| 10/12/15 | | | HOLIDAY | | | |
| 10/13/15 | PW | 17 | Jump start. | 0.5 | \$0.00 | D |
| 10/13/15 | PW | 22 | Take Trk 22 to Jim's Auto Body pick up Trk #24 after bed re-paint. | 1 | \$1,946.05 | D |
| 10/13/15 | PW | 31 | Jump start. | 0.5 | \$0.00 | D |
| 10/13/15 | PW | 25 | Jump start. | 0.5 | \$0.00 | D |
| 10/13/15 | PW | Shop | To A&A Truck to check out plows for tandem dump trks. | 4 | \$0.00 | D,J |

| DATE | DEPT | VEHICLE | REPAIR | Hours | Parts Costs | MECH |
|----------|--------|---------|--|-------|-------------|------|
| 10/13/15 | Police | 1805 | R&R M&B R/rear tire. | 0.5 | \$124.20 | C |
| 10/13/15 | PW | 106 | PM service. | 4 | \$237.51 | C,J |
| 10/13/15 | PW | 23 | Weld dump body sub frame, tabs ect. For mounting of new bed. | 4 | \$0.00 | J,C |
| 10/13/15 | Police | 1808 | Check nail in tire (not into tire,) Check pressure OK. | 0.5 | \$0.00 | C |
| 10/13/15 | PW | 25 | Remove spreader. Body does not dump, no wipers, tarp and headboard are damaged repairs needed. | 1.5 | \$0.00 | J,C |
| 10/14/15 | Fire | 1691 | To BMFC pick up ambulane and take to State Inspection. Pass return to BMFC | 2 | \$0.00 | D |
| 10/14/15 | Police | 1813 | Complete front end rebuild. | 2.5 | \$801.70 | C,D |
| 10/14/15 | PW | 12 | Install neutral safety switch. Troubleshoot no start problem. | 2.5 | \$44.80 | C,D |
| 10/14/15 | PW | 28 | pump fuel out of fuel tank. | 0.5 | \$0.00 | C |
| 10/14/15 | Police | 1813 | PM service, R&R battery, and fuel filter. | 2.5 | \$128.40 | C |
| 10/14/15 | Police | 1808 | PM service, R&R M&B R/rear tire. Scan check engine light. Cat code to Medford ford for repairs under warrenty. | 2.5 | \$152.67 | C |
| 10/14/15 | PW | 23 | Continue of new bed install. | 7 | \$0.00 | J,D |
| 10/14/15 | PW | frklft | Remove blown tire and take to tri-state for repairs. | 1 | \$0.00 | J |
| 10/14/15 | PW | 37 | Road call. | 1 | \$0.00 | J,D |

Projected Work

| | |
|------------------|---|
| Services: | 1610,1807,1805,1816,1833,1811,1804,1835,1834,1801,1812,1818,1809,1823,1813,26,15,12,69. |
| Repairs: | 1803,1806,1692,1693,43,8,10,23,67,25,1800,19,1835,1808,1818. |

This schedule is subject to change, due to unscheduled break downs and repairs, parts and equipment availability.

| | |
|---|-------|
| Total Hours Worked | 85.00 |
| Time Off (e.g., sick, vacation, etc...) | 35 |
| Misc. Time (e.g., Class, CDL Drug Test, etc...) | |

TOTAL HOURS 120.00

TOTAL PARTS COSTS \$6,063.58