

Fleet Status Report

11/20/2015

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
11/12/15	PW	4	Troubleshoot intermitnet inop. Rewire hot wire to fuse box.	1.00	\$0.00	C
11/12/15	PW	330	R&R wiper trans and arms.	2.00	\$256.39	C
11/12/15	Police	1835	PM service.	2.00	\$33.04	C
11/12/15	PW	104	Brake pedal not releasing. Make repairs.	0.50	\$0.00	J
11/12/15	PW	29	R&R power steering cooler, water lines,hydraulic filter. Repair headlights and running lights.	6.00	\$255.48	J
11/12/15	PW	T-1	Jump start and get running, won't start. Bad battery and starter,remove starter send out for rebuild.	2.00	\$0.00	D
11/12/15	PW	35	Jump start and get running.	0.50	\$0.00	D
11/12/15	PW	38	Inflate R/front tire.	1.00	\$0.00	D,J
11/12/15	PW	100	Trouble shoot electrical problem with safety switch on mower head. Contact alamo tech and discuss problem. They will call back.	3.00	\$0.00	D
11/12/15	Fire	1618	Trouble shoot performance problem while driving. Found two blown 20amp fuses. Found a wire shorted out along drives side floor board. Made repairs, replaced fuses test drive OK.	1.50	\$1.78	C
11/12/15	PW	37	Road call, loss of power, got back to shop. Parts ordered.	0.50	\$0.00	D
11/13/15	Fire	1618	Install corner strobe lights.	3.50	\$395.52	C
11/13/15	Police	1837	Go up front and jump battery and bring down back and charge.	1.00	\$0.00	D,C
11/13/15	Fire	1631	R&R alternator, chack charging system.	1.50	\$295.00	D
11/13/15	PW	29	R&R rear marker lights, repair and replace sanding lights.	4.00	\$31.58	J
11/13/15	Police	1830	Go up front and jump battery and bring down back and charge.	1.00	\$0.00	D,C
11/13/15	PW	Shop	Return fire trucks to BMFC and CLFC.	3.00	\$0.00	D,C,J
11/13/15	PW	Shop	Clean shop, Power wash, move equipment, tape off for Rabies Clinic on Sat.	9.50	\$0.00	D,C,J
11/16/15	PW	Shop	Reorganize shop from weekend Rabies Clinic.	3.00	\$0.00	D,C,J
11/16/15	PW	29	R&R High Low headlight switch. Finish wiring and repair to rear sanding lights.Clean up wiring under dash. Remove fuel tank from Trk 28 and install on truck.	6.00	\$9.69	J
11/16/15	PW	102	No running lights at trailer plug. Repaired ground wire.	0.50	\$0.00	J
11/16/15	PW	T-1	Pick up battery from Advance Auto, tighten alt belt. Install starter, check charging system. Good.	3.00	\$307.99	D,C
11/16/15	Fire	1611	Go to BMFC pull out Trk 1611, check for intermittent check engine light. No check engine light on. O fault codes found on manual or auto self test. However on voltage test voltage is at 13.7 volts non loaded. This is marginal. Should be 4.2-4.3. Advised fire co. Waiting for Fire Co to schedule for alt replacement.	1.50	\$0.00	D
11/16/15	Fire	1618	Check operation of Drivers rear LED light. Light is defective. Will need to be replaced. New ones on order.	0.50	\$0.00	D
11/16/15	Water	Bed 67	Secure wires for top led lighting.	2.00	\$0.00	D,C
11/16/15	Animal	1834	Check engine light, Scanned vehicle small evap leak, vehicle was just fueled. Tightened gas cap cleared codes. Will monitor.	0.50	\$0.00	C
11/16/15	Animal	43	Test drive for noise. Pull front wheels. Check brake area. Brake clip on driver side dragging. Adjust clip, test drive still making noise. R&R front brake pads and clips. Test drive, no noise.	3.00	\$44.99	C
11/16/15	Police	1816	R&R Battery check charging system.	1.00	\$93.60	C

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
11/16/15	Fire	1631	Go to CLFC and check switch for cord retractor. Switch is bad, removed switch to use to order new. Parts ordered.	1.00	\$0.00	D
11/17/15	Water	64	PM service. R&R Frt rotors and pads. R&R lower ball joints L&R, R&R Right outer tie rod end. R&R M&B front tires. Not done needs lower control arm. Parts have been ordered.	7	\$513.19	C,D
11/17/15	Police	1813	R&R M&B R/rear tire.	0.5	\$106.92	C
11/17/15	PW	320	R&R water pump, install fuse panel back under dash, reinstall bumper ends. Prep motor for install of new water pump. Parts ordered.	4	\$0.00	J
11/17/15	PW	29	Put fuel back in tank, R&R fuel filter, hook up sander and plow.	1	\$6.39	J
11/17/15	PW	24	R&R blower motor and wheel, blower motor resistor. Check back up alarm	2	\$187.69	D
11/17/15	Water	67	Cut brackets for new body, layout holes for drilling.	1.5	\$0.00	J
11/17/15	PW	29 Plow	Put plow on truck 29 for repairs ro be done.	1	\$0.00	D,R
11/17/15	PW	33	Remove center control panel, check fuses and relays. Remove head light switch, repair plug connection, reassemble as needed.	2	\$0.00	D
11/17/15	Fire	1631	R&R switch for reel.	1.5	\$12.07	D
11/18/15	Police	1835	Go to OOS cars and remove computer. Remove computer in 1835 install spare computer. Fuse still blowing, trouble shoot electrical sustum. Circuit #21.	3.5	\$0.00	D,C
11/18/15	PW	37	R&R Fuel line, R&R Fuel Filter.	2	\$109.61	D,C
11/18/15	PW	24	R&R Back up alarm. Trouble shoot electrical system, no running lights or reverse lights. Tail lights to be replaced. Have parts. Not completed.	4	\$22.75	D,C
11/18/15	PW	320	Install water pump. Top off fluids as needed.	3.5	\$448.89	J
11/18/15	PW	67	Drill and mount body mounting brackets to truck. Mount body on truck.	6	\$0.00	J,D,C
11/18/15	PW	19	Trouble shoot inop tail lights. Make repairs as needed.	2	\$0.00	D
11/18/15	Fire	1611	Remove alternator. Service battery cables and batteries.	1.5	\$0.00	D
11/18/15	PW	13	Install diesel retrofit tags on vehicle. One under hood, one on muffler.	0.5	\$0.00	D

Projected Work

Services	1838,1807,1834,28,27,40,19.
Repairs	10,8,24,1806,1804,1611,1615,67,23,1692,320.

This schedule is subject to change, due to unscheduled break downs and repairs, parts and equipment availability.

Total Hours Worked	109.00
Time Off (e.g., sick, vacation, etc...)	40
Misc. Time (e.g., Class, CDL Drug Test, etc...)	

TOTAL HOURS 149.00

TOTAL PARTS COSTS \$3,132.57