

FLEET STATUS REPORT

10/17/2016

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
09/29/16	PW	Shop	Training and demo on new Leeboy paver.	1.50	\$0.00	DD,D,J
09/29/16	PW	105	Replace rubber sheild on mower deck.	0.50	\$132.09	J
09/29/16	Police	1809	PM service, replace R.R. tire.	3.00	\$182.11	J
09/29/16	Police	1814	Free up emergency brake cables and acuators.	2.50	\$0.00	J
09/29/16	Police	1801	Replace hardware for shotgun rack.	0.50	\$2.00	DD,D,J
09/29/16	Police	old1801	Reclock wiper motor linkage, replace washer pump, repair vacuum leak.	2.00	\$20.78	DD,D,J
09/29/16	PW	chn saw	check recoil pull start. (needs parts)	1.50	\$2.29	D
09/29/16	Police	1811	Replace R and L updraft oxygen sensors, clear codes and test drive.	2	\$243.84	D
09/30/16	PW	111	Pick up and install front cab door.	1.5	\$90.00	D,DD
09/30/16	PW	Jdwasher	Found bad check valve cartridges(needs parts ordered)	1.5	\$0.00	J
09/30/16	PW	Shop	Wellness Fair.	1.5	\$0.00	D,J
09/30/16	PW	22	remove spare and replace with new tire.	1	\$24.75	J
09/30/16	PW	29	Replace mud flap.	1	\$0.00	J
09/30/16	PW	105	Reconnect mower feed door with new hardware.	1	\$1.70	J
09/30/16	PW	Shop	To Thompsons Welding, pick up metal for snow plow repairs.	0.5	\$230.00	J
09/30/16	Police	1803	PM service,replace R.S. mirror, front brake job, repair threads on calipers.	3.5	\$77.53	D
09/30/16	Police	1802	Place unit number decals on door sides.	0.5	\$1.38	D
10/03/16	PW	38	PM service.	3.5	\$308.70	J
10/03/16	PW	plow10	Weld angle iron on plow base for rubber and plate installation.	1	\$0.00	J
10/03/16	PW	frklft	Charge battery, clean terminals, repair burnt wire.	1	\$0.00	J
10/03/16	PW	T31	Repair wire harness at master switch.	1	\$0.00	D
10/03/16	PW	106	Power wash track area, replace all bottom rollers, go to Groff for parts.	6.5	\$107.50	D,J
10/04/16	PW	36	Check brake pedal going to floor, check for leaks, bad master cylinder.	2	\$0.00	J
10/04/16	PW	105	Remove front tires from tractor for replacement.	0.5	\$0.00	J
10/04/16	PW	38	Finish PM service, replace 3 grease fittings and clean out to take grease.	4	\$9.28	J
10/04/16	PW	37	Remove cab fan, tear apart and try to get working.	0.5	\$0.00	D
10/04/16	PW	Shop	Change out grease drum and clean up unit.	1	\$0.00	D
10/04/16	PW	106	PM service, weld broken hood hinges.	4	\$107.16	D
10/04/16	Police	1813	Repair brake light switch, noise in L.F. tire (air sensor fault).	1	\$0.00	D
10/05/16	PW	T31	Replace 33 cutters and 15 holders.	4	\$522.54	J,R
10/05/16	PW	36	Bolt inner fender back together, top off all fluids.	1	\$0.00	J
10/05/16	PW	T6	Replace fuel line, drain tank, clean and refill, lube unit.	1	\$13.75	J
10/05/16	PW	frklft	Replace starter.	1	\$185.00	J
10/05/16	Water	68	Remove lines, get new lines made at Hainesport Truck, replace lines.	2	\$189.16	DD

FLEET STATUS REPORT

10/17/2016

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
------	------	---------	--------	-------	-------------	------

Projected Work : Truck #3 Running poorly, Truck #21 Fuel tank, T16 Teeth & Hammers, Truck #5 Seat & brake check, Plows #102,14,10 Structural repairs, #38 Backhoe Hydraulic cooler, Truck #4 Replace 4 tires, check shifter, PM's on front line police vehicles.

Total Hours Worked	60.50
Time Off (e.g., sick, vacation, etc...)	56.5
Misc. Time (e.g., Class, CDL Drug Test, etc...)	1.5

TOTAL HOURS 118.50

TOTAL PARTS COSTS \$2,451.56