

Fleet Status Report

3/1/2016

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
02/18/16	PW	26	Repair tarp. Parts ordered. Useable.	2.50	\$0.38	D
02/18/16	PW	26	PM service. No marker lights. Taking sander off and washing will bring back in later for marker lights.	2.00	\$238.86	J
02/18/16	PW	19	Finish service, finish install of air dryer, no side strobes on body. New LED lights to be ordered and mounted,	2.00	\$0.00	J
02/18/16	PW	38	Re-seat right front tire, air up to specs.	1.00	\$0.00	A,D
02/18/16	PW	17	Check windshield, has scratches, may be able to have buffed out. Will take to creekside for evaluation.	0.50	\$0.00	D
02/18/16	PW	34	Jump start, get running. Charge batteries and plug in.	1.00	\$0.00	A,D
2/18/2016	PW	18	Pull in shop and remove seat for repair.	2.00	\$0.00	A,D
02/18/16	PW	37	Work on oil leaks at top of motor.	3.50	\$53.76	J
02/18/16	PW	102	PM service.	2.00	\$42.83	C
02/18/16	PW	19	Remove and replace pressure relief valve.	1.00	\$261.50	C
02/18/16	PW	66	Jump start get running.	1.00	\$0.00	C,A
02/18/16	Police	1801	Take off repair rear fender flare.	0.50	\$0.00	C
02/18/16	PW	7	Fuel truck, aircompressor, and welder.	0.50	\$0.00	C
02/18/16	Fire	1601	Check brakes for noise. Can not duplicate. Pull all wheels do visual inspection of brakes. No problem found. Test drive, brakes good. Troubleshoot air bag light.	1.50	\$0.00	C
02/18/16	Police	1806	PM service. Repair third brake light, replace bulbs in thrid brake light.	2.50	\$29.91	A,D
02/18/16	PW	31	Remove bucket, weld pins for hydraulic cylinder stops for bucket coupler.	3.00	\$0.00	A,D
02/18/16	PW	Shop	Do trash run, clean up metal, clean up shop.	1.00	\$0.00	A,C
02/19/16	PW	37	Finish install of valve cover gasket and breather on valve cover. Ok to use. Needs more work to be done. Will be scheduled.	5.00	\$51.14	J,D
02/19/16	PW	33	Try to get running to bring in shop for repairs. replace batteries, will not start, remove and service battery cables still no start. Troubleshoot, not completed.	5.50	\$0.00	J,D
02/19/16	Fire	1602	Check and top off fluids, Replace bulbs in repair rear tail light assy,	1.00	\$5.46	A
02/19/16	PW	25	Road call air up front tire. Vehicle also has a rear inner dual flat.	1.00	\$0.00	A,C
02/19/16	Police	1811	PM service, Remove and replace, mount and balance Left rear tire.	2.50	\$157.51	C
02/19/16	Police	1801	PM Service.	2.00	\$32.32	A
02/19/16	PW	26 Sndr	Get information off sander for parts to be orderd.	0.50	\$0.00	D
02/19/16	PW	31	Check operation of hydraulic bucket locking ram, while operator changes.	1.00	\$0.00	A,D
02/19/16	PW	18	Take seat to Al's Trim shop.	1.00	\$0.00	D
02/19/16	Code	52	PM service, Remove and replace wiper blades and fuel filter.	2.50	\$45.64	C

Fleet Status Report

3/1/2016

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
02/19/16	Police	1802	PM service, Remove and replace, Mount and Balance front tires. Vehicle has coolant leak. Needs lower rad hose to oil cooler. Parts ordered.	3.00	\$242.10	C
02/19/16	Police	1801	Remove and replace R/rear fender flare moulding.	1.00	\$90.88	C
02/22/16	Police	1813	Remove and replace R/rear turnsignal bulbs,	0.5	\$3.66	J
02/22/16	PW	26	Troubleshoot and repair body electric lighting problem. Make repairs in harness as needed. Repair License plate light.	7	\$14.05	J,D
02/22/16	Fire	1601	To Craigs auto for air bag repair.	1	\$0.00	D,C
02/22/16	Fire	1615	Pick up from Blaze and return to Fire House after repairs.	2	\$0.00	D,J
02/22/16	PW	24	Repair wiring and connectors to rear tail lights.	2	\$0.00	D
02/22/16	PW	101	PM service.	2	\$42.83	C
02/22/16	Police	1807	PM service, Remove and replace #4 coil pack, and front 3 spark plugs, repair light bar. Repair front Radar antenna.	4	\$149.22	C
02/23/16	PW	26	Re-install wiring harness after repairs. Tape up and wire tie in place. Repair oil leak at dump cylinder. Check and tighten fittings.	4	\$4.26	J,D
02/23/16	Fire	1611	Pick vehicle up from Fire house, bring to shop for repairs. Remove and replace left rear compartment door switch.	4.5	\$68.15	D,J,C
02/23/16	PW	36	Remove tire from vehicle. Remove and replace valve stem. Re-install on vehicle. Put vehicle back in service.	1	\$0.76	J
02/23/16	Water	61	PM service. Remove and replace fuel filter. Needs new clip for fuel filter. Parts have been ordered.	3	\$49.13	J
2/23/16	PW	25	Go to tire shed and locate spare tire for truck. Remove and replace Right/rear inner tire. Spare was used but in good shape.	1	\$0.00	D,J
	Police		PM service. Vehicle also had check engine light for overheating. Pressure test cooling system. No leaks found. Pressure test Rad cap, losing pressure, remove and replace rad cap. Let vehicle run and check for leaks or overheating. None found. Remove and replace front tires Left and right. Mount and balance tires re-install on vehicle. Put vehicle back in service.	3.5		
02/23/16		1813			\$242.10	C
02/23/16	Water	70	PM service.	2	\$36.42	C
02/23/16	Police	1807	Jump start. Test drive and check charging system ok. Back in service.	0.5	\$0.00	C
02/23/16	PW	Shop	Go to Al's Trim Shop and pick up seat for truck #18.	0.5	\$0.00	C
	PW		Put vehicle up on jack stands remove all wheels. Disassemble rear brakes, backing plates, and brake lines. Remove rear leaf spring assembly Left and Right,	9.5		
02/24/16		20	Remove front brake componets, Left and Right.		\$0.00	J,D
	Police		Go up front and get vehicle. Not running. Get running and bring to shop.	2		
02/24/16		1818	Troubleshoot for no charging. Needs Alternator. Parts ordered. Remove and Replace Alternator. Check charging system. Good.		\$145.00	C

Fleet Status Report

3/1/2016

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
02/24/16	Police	1802	Remove and replace oil cooler hose. Top off antifreeze as needed.	2	\$34.30	C
02/24/16	PW	18	Install re-upholstered seat, seatbelts etc.	2	\$300.00	A,C
	PW		Install tags put reg and insurance card in vehicle. Install carbon canister fresh air kit. Remove snow plow, install plow controler hanger. Check all fluids. Secure wires	3.5	\$0.25	
02/24/16		204	for LED lights in ready box.			D
02/24/16	Admin	2	PM service. Remove and replace wiper blades.	2.5	\$43.20	A
02/24/16	PW	Shop	Check PW vehicles for registrtrions and insurance card, and inspections.	1.5	\$0.00	A
02/24/16	PW	15	Remove and repair left rear tail light.	0.5	\$1.83	A
	PW		Take to Creekside glass to inspect windshield. Can not be repaired needs to be replaced. Remove and repair cargo light bulb. Repair front air dam.	1.5	\$1.99	A
02/24/16	PW	17	Take spare tire and rim 11-22.5 to Tri-State for mount and dismount w/new valve stem.	1	\$24.75	C
02/24/16	PW	Shop	Take discarded tires and put in tire trailer. Do trash run.	1	\$0.00	C,A

Projected work;
 Services;1618, 1610, 41, 1805, 1803, 8709, 16, 112, 15.
 Repairs; 4, 17, 21, 22, 33, 20, 1810, 1804, 101, 11, 28.

Total Hours Worked	119.00
Time Off (e.g., sick, vacation, etc...)	16
Misc. Time (e.g., Class, CDL Drug Test, etc...)	

TOTAL HOURS 135.00

TOTAL PARTS COSTS \$2,414.19

(PM - Preventive Maintenance, LED - Light Emitting Diode)