

FLEET STATUS REPORT

4/10/2017

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
03/23/17	Fire	1831	Jump start, pull outside and let run.	0.50		J
			Remove and replace intake manifold and gasket. Remove and replace thermostat and gasket. Remove and replace thermostat housing. Remove and replace spark plugs and boots. Test drive.	5.00	\$403.35	C
03/23/17	Police	1819	Pick up from Medford Ford. Check codes, random misfire, possible foul plugs.	1.00		C
03/23/17	PW	Shop	Clean blood in Sunbury.	0.50		C
03/23/17	Water	69	Check brakes, unit needs PM service and lower ball joints.	0.50		D
03/23/17	PW	111	Repair broken cab door latch.	1.50	\$0.10	D
			Replace right rear hub assembly. Repair damaged control arm yoke. Repair dented right rear rim. Replace right rear tire and dismount spare. Put used tire on spare.	3.50	\$233.91	D
03/23/17	PW	12	Get unit running. Replace missing clip on intake.	0.5	\$7.49	D
			Troubleshoot back up air system and compressors. Check air system for leaks.			
03/24/17	Fire	1831	Bring unit back to Country Lakes Fire Dept.	5.5		D, DD
			Remove and replace coils and spark plugs. Reset misfire monitor with scan tool.			
03/24/17	Police	1816	Test drive.	1.5	\$603.78	C
03/24/17	Police	1811	Check with scan tool. Reset misfire monitor. Test drive.	1		C
03/24/17	Police	1842	Check for draw.	1.5		C
03/24/17	PW	16	Rewire headlights. Replace right rear brake light bulb. Replaced turn signal flasher.	2.5	\$1.99	C
03/24/17	PW	31	Clean bay and bring loader in for center pins	1		J
			Replace air switch for brake lights. Remove spare tire on right front and mount original tire back on.	1.5	\$803.80	J
03/24/17	Water	69	Replace front brakes and calipers. Preventive maintenance service. Adjust rear brakes. Check engine light on - old code, clear.	3	\$154.14	J
03/24/17	PW	21	Make fuel gauge operational.	0.5	\$3.45	J
			Blown hydraulic hose, go to Hainesport to have hoses made. Remove front left tire and drop off at Tri State for repair.	3	\$220.84	J
03/27/17	PW	31	Disassemble and split for center pins.	17.5		J, D, DD
03/28/17	PW	31	Replace center bearings	13		D, DD
03/28/17	Police	1813	Diagnose steering shaft	0.5		C
03/28/17	Police	1810	Preventive maintenance service	2.5	\$31.33	C
			Remove and replace rear calipers. Replace brake line from the ABS pump to the right front wheel. Bled ABS pump with scan tool. Bled brakes.	4.5	\$148.88	C, D, J
03/28/17	Police	1390	Take number of filters. Repair wiper.	3.5	\$1.58	J
03/28/17	PW	109	Air up flat tire and check all air pressures.	0.5		J

FLEET STATUS REPORT

4/10/2017

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
03/28/17	PW	38	Pick up tire from Tri State, take to Presidential Lakes and install.	1	\$57.90	J
03/28/17	Fire	1636	Pick up from Country Lakes Firehouse troubleshoot vehicle is sluggish.	1		J
03/29/17	Fire	1612	Install land line charging unit.	1.5	\$622.83	DD
03/29/17	PW	31	Finish reassembling center pins and steering motor.	14		J, D, DD
			Finish repairing wiper. Repair hood lights. Repair engine hood due to hinge being			
03/29/17	PW	109	froze up.	2	\$23.18	J
03/29/17	Police	1812	Preventive maintenance service	2	\$28.60	C
03/29/17	Police	1813	Remove and replace inner steering shaft	0.5	\$210.31	C
03/29/17	PW	16	Remove fuse	0.5		C
			Remove and replace rack and pinion. Remove and replace power steering pump.			
03/29/17	Police	1810	Remove and replace power steering high pressure line.	3.5	\$408.97	C
			Total Hours Worked			
						102
			Time Off (e.g., sick, vacation, etc...)			12
			Misc. Time (e.g., Class, CDL Drug Test, etc...)			
						<hr/>
			TOTAL HOURS			114
			TOTAL PARTS COST		\$3,966.43	