

Fleet Status Report

9/12/2016

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
09/01/16	PW	# 24 Plow	Check over for snow season.	2.00	\$16.14	J
09/01/16	Fire	1815	Check out light problem.	2.00		J, C
09/01/16	PW	26	Replace right rear outside tire that was flat.	0.50		D
09/01/16	Police	1803	Replace wiper motor and wiper transmission.	1.50	\$284.59	D
09/01/16	PW	35	Power wash and degrease two loader lift cylinders. Start removing cylinders to be rebuilt. Free up seized rod eye pins to be removed.	5.50	\$5.99	D, J
09/01/16	PW	#23 Plow	Check over for snow season.	0.50		J
09/01/16	PW	#25 Plow	Check over for snow season.	1.50	\$18.75	J
09/01/16	PW	104	Repair and air up front tire.	2.00	\$1.50	J, C
09/01/16	Fire	1800	Replace wiper blades.	0.50	\$9.36	C
09/01/16	Police	1812	Preventive maintenance service. Mount and balance two tires. Replace front pads and rotors.	4.00	\$489.95	C
09/02/16	PW	35	Heat and extract seized loader. Lift cylinder pins. Remove left lift cylinder for repairs.	5.50	\$5.99	D, J
09/02/16	PW	Shop	Clean shop and wash shop truck.	2.50		D
09/02/16	Police	1820	Preventive maintenance service.	1.00	\$28.51	C
09/02/16	Police	1808	Preventive maintenance service.	2.00	\$28.51	C
09/02/16	PW	T-1	Get information off of loader for ordering parts.	0.50		J
09/02/16	PW	#24 Plow	Remove and replace wheel bearings.	1.00	\$81.04	J
09/02/16	PW	#23 Plow	Remove and replace wheel bearings.	1.00	\$18.28	J
09/02/16	Police	1813	Mount and balance two tires.	1.00	\$184.00	C
09/02/16	Police	1810	Load test battery. Battery does not hold a load. Replace battery. Check battery voltage after replacement. Replaced TPMS mounting kit. Test drive.	1.00	\$128.92	C
09/02/16	Fire	1815	Replace two spot light bulbs.	1.50	\$19.00	C
09/06/16	PW	#25 Plow	Remove and replace wheel bearings.	2.00	\$143.80	J
09/06/16	PW	#22 Plow	Check over for snow season. Remove and replace wheel bearings. Remove and replace gauge wheel adjusters.	4.50	\$145.86	J
09/06/16	PW	19	Check fuel leak. Tighten loose fuel filter. Check service light on.	0.50		D
09/06/16	PW	35	Reseal LH loader lift cylinder.	1.50	\$104.68	D
09/06/16	PW	107	Road Call Sheep Pen Hill Road. Check unit not charging. Replace alternator and charge battery.	3.50	\$175.00	D

Fleet Status Report

9/12/2016

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
09/06/16	PW	37	Change right front tire that was flat.	1.50		D, J
09/06/16	Police	1855	Spotlight switch inoperable. Remove and replace switch. Troubleshoot check engine light. Evap small leak. Tightened gas cap, cleared codes.	1.50		C
09/06/16	PW	Shop	Took scrap and tires out.	0.50		C
09/06/16	Police	1809	Preventive maintenance service. Replace front brake pads.	3.00	\$77.70	C
09/06/16	Police	1811	Replace left front headlight bulb. Troubleshoot check engine light.	0.50	\$6.99	C
09/06/16	Police	1818	Replace starter.	1.00		C
09/07/16	PW	Shop	Remove batteries and look for gas keys from junk vehicles.	1.00		C
09/07/16		Shop	Went to Tri-State to pick up tires.	2.00		C, DD
09/07/16	PW	1812 1836 1838	Went to Browns Mills Firehouse, Country Lakes Firehouse and Tri-State. Went to Browns Mills Firehouse to check out 1812. Went to Country Lakes to check out 1836 and 1838.	4.00		C, DD
09/07/16	Fire	1818	Disarm security system. Look up wiring diagram and took plastic off of steering column for alarm system.	5.00		C, DD
09/07/16	PW	35	Rebuild lift cylinders.	6		D
09/07/16	Water	68	Adjust emergency brake.	0.5		J
09/07/16	PW	#68 Plow	Check over for snow season.	1		J, D
09/07/16	PW	#21 Plow	Check over for snow season.	1	\$18.28	J
09/07/16	PW	#29 Plow	Check over for snow season.	1		J
09/07/16	PW	#26 Plow	Remove and replace wheel bearings.	2	\$157.15	J

Total Hours Worked	80.50
Time Off (e.g., sick, vacation, etc....)	28
Misc. Time (e.g., Class, CDL Drug Test, etc....)	

TOTAL HOURS 108.50

TOTAL PARTS COSTS \$2,149.99