

Fleet Status Report

3/30/2016

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
03/17/16	PW	Shop	Office time.	2.50		A
03/17/16	Police	1811	Repair mic holder.	0.50		A
03/17/16	PW	12	Mount and balance four tires. Install valve stems.	3.00	\$683.72	D, A
03/17/16	Water	63	Remove broken stud in head for exhaust manifold. Tap threads in all bolt holes; clean head surface. Install new exhaust studs with anti-seize.	4.00		D, A
03/17/16	Police	1812	Repair flash light charger.	0.50		D
03/17/16	Police	1816	Preventive maintenance service. Tag light bulb out.	2.00	\$32.12	D
03/17/16	PW	106	Install new bottom plate in bucket. Cut out plate and fit to bucket. Install plate and start to weld in.	6.50	\$7.99	J
03/17/16	Water	old 63	Remove left front exhaust manifold.	4.00		C
03/18/16	PW	Shop	Check insurance cards and registrations on police motorcycle trailer, M1, M2 and M3. Replace insurance cards in all four and registration card in trailer.	1.00		D
03/18/16	PW	28	Road call to BMIA building. Repair left rear tail light.	2.00	\$12.00	A, D
03/18/16	PW	32	Jump start.	0.50		A
03/18/16	Fire	1815	Start, let run. Take to Blaze for check engine light. Loss of power.	2.00		A, D
03/18/16	PW	Shop	Put plows and spreaders on 22, 23, 24, 25, 26 and 67.	8.50		A, D, J
03/18/16	PW	10	Check for antifreeze leak. Overflow tank leaking. Leaking out of cap. Too much antifreeze. Remove some antifreeze.	0.50		A
03/18/16	PW	Shop	Office time.	1.00		A
03/18/16	PW	110	Tighten friction bolt on hydro handle.	1.00		J
03/18/16	PW	106	Continue welding bucket.	5.00		J
03/21/16	PW	106	Continue welding bucket. Pick up welding rod at Clydesdale. Pick up steel from Thompson's Welding.	6.00		J
03/21/16	PW	40	Would not start. Bad connection at fuse box.	0.50		J
03/21/16	PW	old 63	Install left front exhaust manifold. Install EGR inlet tube. Remove brake line for the rear and front brakes. Make brake line for rear and front brakes. Bleed brakes.	6.00	\$80.36	C
03/21/16	PW	16	Swap out broken fuel filter cap and fuel filter under hood. Off lift inspection. Repair left rear park light.	1.50	\$91.60	D
03/21/16	PW	22	Remove old heat shield, measure, cut and modify to fit new style emissions muffler.	4.50		D, A
03/21/16	PW	Shop	Replace break away on number 1 gas pump.	1.00		D, C
03/21/16	PW	63	Repair shift indicator. Remove and replace reverse bulb. Install tag light.	3.00		C
03/21/16	Fire	1603	To Lucas Dodge for recall.	2.00		A, D
03/21/16	Fire	1603	Back to Dodge with keys.	1.00		A

Fleet Status Report

3/30/2016

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
03/21/16	PW	Shop	Weld adjustable arm on lift. Grind off old welds/weld arm and paint.	1.50		A
03/21/16	PW	Shop	Office time.	2.00		A
03/22/16	Police	1806	Jump start. Remove transmission.	3.5		C
03/22/16	PW	106	Weld bucket.	6.5		J
03/22/16	Police	1814	Take to Lucas Dodge for recall. (Air bag system.)	0.5		D
03/22/16	Fire	1603	Pick up from Lucas Dodge after recall repairs. (Air bag system.)	0.5		D
03/22/16	PW	22	Finish heat shield. Check left side plow light.	3.5	\$4.57	D
03/22/16	Fire	1815	Take fuel filters to Blaze, discuss problems with truck 1815.	2	\$49.45	A, D
03/22/16	PW	Shop	Office time.	5		A
03/23/16	Police	1810	Remove and install transmission. Install used battery.	6.5	\$10.20	C
03/23/16	PW	Shop	Office time.	5		A
03/23/16	Police	131	Pick up from Lucas Dodge after recall repairs. (Air bag system.)	1		D
03/23/16	Police	1855	Take to Lucas Dodge for recall. (Air bag system.)	0.5		D
03/23/16	PW	24	Check trailer electrical connector for compatibility with Falcon Asphalt Heater.	1.5		D
03/23/16	PW	104	Road call to beach house. Refuel tractor.	2		A, D
03/23/16	PW	Shop	To Clydesdale for welding rods.	0.5		D
03/23/16	Police	1814	Pick up from Lucas after recall repairs. Check codes.	1.5		D
03/23/16	PW	106	Continue welding bucket.	6.5		J

Total Hours Worked	120.00
Time Off (e.g., sick, vacation, etc....)	12
Misc. Time (e.g., Class, CDL Drug Test, etc....)	

TOTAL HOURS 132.00

TOTAL PARTS COSTS \$972.01