

**Water Division
Status Report
12/09/2015 – 12/15/2015**

Mark Outs for Street Excavations by PTMUA, PSE&G and JCP&L:

- | | | |
|-----------------------------|---------------------------|---------------------|
| • 115 Oak Pines (Emergency) | • 3 Morton Rd (Emergency) | • 2 Pine Mill Rd |
| • 6 Woodland Avenue | • Woodland Avenue | • 11 Sage Street |
| • University Avenue | • 19-31 Scammel Drive | • 5 Juliustown Road |
| • 47 Four Mile Road | • | • |
| • | • | • |
| • | • | • |

Water Meters:

- Completed meter readings in Books 25 & 26 (Lake Valley)
- Continued meter readings in Books 1 & 2 (Evergreen)
- Final reading at 32 Rancocas Lane,
- Re-read 218 Tremont Street and 248 DelMar Avenue

Water Turn On/Turn Off:

- Turn on 100 PBM Road, Unit Q

Water Wells:

- Daily routine well checks morning/afternoon
- Added chlorine and polyphosphate to wells as needed
- Replenished chemical supplies at wells
- Water samples
- Removed leaves from wells

Miscellaneous:

- Repaired water valve key
- Checked for leak at 115 Oak Pines – on resident's side
- Transported truck #69 to Medford Ford and back to Water Garage
- Swept Water Garage/Office
- Assisted water reader
- Checked for leak at 201 Scammel – Turned water on all the way
- Located, jack hammered and raised valve on Lakehurst Road
- Located shut offs on South Brynwood Drive
- Cleaned and organized truck #62

- Repaired valve box on Waverly
- Cleaned trucks and garage
- Replaced service lines at 1101 S. Brynwood, 1501 S Brynwood, 1300 S Brynwood and 1500 S. Brynwood
- Located and dug up 1203 S. Brynwood service line to ensure on 8"
- Patched holes on S Brynwood and removed old blacktop
- Assembled parts for new connection 13 Arney's Mt. Rd.