

**Water Division  
Status Report  
04/19/2017 – 04/25/2017**

**Mark Outs for Street Excavations by PTMUA, PSE&G and JCP&L:**

- 141 Oak Pines Blvd
- 701 Concord Drive
- 162 Heather Street
- 55 Lakehurst Road
- 350 Salvia Street
- 235 Amherst Avenue
- 133 N. Pemberton Road
- 130 Clubhouse Road
- 113 Hanover Blvd
- 701 Concord Drive
- 59 Ridge Road
- 70 Scrapetown Road
- 212 Sunset Street
- 150 Garden Avenue
- 347 Pemberton Blvd
- N. Pemberton Road

**Water Meters:**

- Completed meter readings in Books 11 & 12 (North Lakeshore/Browns Mills)
- Continued meter readings in Books 13 & 14 (East Lakeshore)
- Final readings: 334 Snow Ave., 50 Berkshire St., 243 Amherst Ave., 6 Wenatchi Trl., and 150 Juniper Ave.,
- Replaced water meter set at 77 Garfield Blvd and 229 LaFayette Avenue

**Water Turn On/Turn Off:**

- Turned on 20 Fort Dix Road
- Turned on 210 Hargrove Avenue
- Turned on 10 Talapoosa Trail
- Turned off 502 Berkeley Drive
- Turned off 211 Palm Avenue

**Water Wells:**

- Daily routine well checks morning/afternoon
- Added chlorine and polyphosphate to wells as needed
- Replenished chemical supplies at wells
- Water Samples
- Static water tests at Well #1, Well #4 and Well #11
- Cleaned up well yard at Well #11

**Miscellaneous:**

- Installed meter box and meter at 116 Pin Oak Dr., 117 Pin Oak Dr., 119 Pin Oak Dr., and 121 Pin Oak Dr.
- Cut road at Split Rock/Firehouse Road for pipe installation
- Took photos of Pemberton Heights meter and took measurements for firehouse
- Two laborers attended Excavating, Trenching and Shoring Class
- Relocated pallet of pipe for installation on Split Rock Road
- Flushed fire hydrant on Brook Street
- Assembled 8" valve for installation on Split Rock Road
- Distributed water interruption notices on Split Rock and Firehouse Roads

- Cleaned the shop and trucks
- Assembled parts
- Installed 8" valve and 8" pipe on Split Rock Road. Patched hole on Split Rock Road.
- Flushed water main on Split Rock and Firehouse Roads.
- Picked up load of cold patch
- Assembled fire hydrant for installation on Split Rock Road
- Loaded backhoe forks on truck
- Cleaned and performed maintenance on trucks
- Checked 211 Palm Avenue for leak